



SUBJECT SITE:	Tomlinson Middle School 200 Unquowa Road Fairfield, CT
CLIENT:	Fairfield Public Schools 418 Meadow ST. Fairfield, CT 06824.
INSPECTION DATE:	February 15, 2019
BIG EAST PROJECT #:	19085

Limited Asbestos Inspection

Big East Environmental, LLC performed a limited asbestos inspection at the above referenced subject property. The inspection was limited to Sound Wall panels in the music room of Tomlinson Middle School. The inspection was performed according to the State of Connecticut and federal asbestos NESHAP regulations. Suspect asbestos-containing materials were sampled and analyzed at SanAir Technologies by EPA 600/R-93/116 method using Polarized Light Microscopy.

Table I – Asbestos Containing Materials

The following table represents sampled building materials that fall under the state and federal definition of asbestos containing material.

ID	DESCRIPTION	LOCATION	SF/LFT*	% ASBESTOS	CONDITION
NA	NA	NA	NA	NA	NA

*Contractor shall verify all quantities prior to state notification. All SF/ LF amounts are estimates.
F – Friable NF – Non-friable

REGULATORY INFORMATION

The regulations of CT Department of Public Health and the US EPA define asbestos containing materials (ACM's) as materials containing greater than 1% asbestos (*chrysotile, amosite, crocidolite, anthophyllite, actinolite or tremolite*). If one or more bulk samples of a homogeneous material are found to contain greater than 1% asbestos, then all of the homogeneous material is classified as ACM.

FINDINGS SUMMARY

Asbestos containing materials HAVE NOT been identified.

Table II – Non-Asbestos Containing Materials

The following table represents sampled building materials that were tested and do not fall under state or federal definition of asbestos containing material.

SAMPLE ID	DESCRIPTION	LOCATION
WP1	Wall Panel 1 (5x8)	Music Room: Back Wall at floor level
WP2	Wall Panel 2 (Fabric panel)	All Walls, Upper section

Please feel free to contact us at any time if you have any questions regarding this investigation.



Sincerely,

Eric Gelhaus
Project Manager
CT Asbestos Inspector – License #000962

LIMITATIONS

Big East Environmental strives to conduct a thorough, comprehensive inspection, some exclusions are warranted. For 100% accuracy in the determination of ACM, 100 % demolition would be necessary to access all materials. There is always a possibility that asbestos is present within areas that we could not access. Big East shall not be held liable for abatement costs related to additional asbestos not identified in this report. Big East Environmental is not liable for building materials damaged during the course of the survey in the effort to find hazardous materials.



SanAir ID Number
19007260
 FINAL REPORT
 2/20/2019 3:01:31 PM

Name: Big East Environmental
Address: 57 Chestnut Street
 Unit #10
 Norwalk, CT 06854
Phone: 203-354-4955

Project Number: 19085
P.O. Number:
Project Name: Tomlinson Middle School, Unquowa Rd,
 Fairfield
Collected Date: 2/15/2019
Received Date: 2/18/2019 8:55:00 AM

Analyst: Tallert, Jonathan

Asbestos Bulk PLM NY ELAP 198.1

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
WP1-01 / 19007260-001 Wall Panel 1 (5x8 Panel) Back Wall At Floor	Tan Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
WP1-02 / 19007260-002 Wall Panel 1 (5x8 Panel) Back Wall At Floor	Tan Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
WP1-03 / 19007260-003 Wall Panel 1 (5x8 Panel) Back Wall At Floor	Tan Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
WP2-01 / 19007260-004 Wall Panel 2 (Fabric Panel Cloth) All Walls, Upper Section	White Fibrous Homogeneous	90% Glass	10% Other	None Detected
WP2-02 / 19007260-005 Wall Panel 2 (Fabric Panel Cloth) All Walls, Upper Section	White Fibrous Homogeneous	90% Glass	10% Other	None Detected
WP2-03 / 19007260-006 Wall Panel 2 (Fabric Panel Cloth) All Walls, Upper Section	White Fibrous Homogeneous	90% Glass	10% Other	None Detected

Analyst:

Approved Signatory:

Analysis Date: 2/20/2019

Date: 2/20/2019



68 Water Street, Unit F
 Norwalk, CT 06854
 203.354.4955 office
 contact@bigeastlabs.com

190072eD

Date of Collection: 2/15/19	Analysis: <input type="radio"/> PLM <input type="radio"/> TEM NOB <input checked="" type="radio"/> NYS Protocol <input type="radio"/> Other
Project ID: 19085 Site Address: Tomlinson Middle School, 200 Virginia Rd, Fairfield	TAT <input type="radio"/> 3hr <input checked="" type="radio"/> 24hr <input type="radio"/> 5 day <input type="radio"/> 6hr <input checked="" type="radio"/> 48hr <input type="radio"/> Other _____ <input type="radio"/> 12hr <input type="radio"/> 72hr
Inspector: Eric Gelhaus	Lab Instruction: <input checked="" type="radio"/> Positive Stop per Homog Area <input checked="" type="radio"/> Analyze by layer listed layers only <input type="radio"/> Other

BULK SAMPLE CHAIN OF CUSTODY

Homog ID	Sample #	Description	Location	SF/LF
WP1	01	Wall Panel 1 (scr, spigetti like panel)	Back wall at bar level, Music Room	520 SF
	02	↓	↓	↓
	03	↓	↓	↓
WP2	01	Wall Panel 2 (fabric panel joint)	Perimeter ^{All} walls, upper section	600 SF
	02	↓	↓	↓
	03	↓	↓	↓

MB 855A FEB 18 2019