



Toni R. Jones Ed. D.
Superintendent of Schools

December 14, 2018

Dear Dwight Families,

We are pleased to report that Room 10 is now odor-free. It was determined that the odor was emanating from fibrous walls. The temperature of the air conditioning unit in Room 10 had been set too low, resulting in the formation of extensive condensation on the fibrous walls and causing the odor. The affected walls were removed and replaced with new drywall. Principal Maniscalco has also inspected the room and cleared it for use. As a reminder, there was no mold or unsafe growth in the room. The challenge was to determine the location and source of the odor, which was accomplished after a thorough investigative process.

In addition, the pipes in the front restrooms have been replaced and the project is expected to be complete after winter break.

The next step is addressing the piping in the mechanical chase in the staff bathrooms.

Thank you again for your patience as we work through and resolve important maintenance issues for our Dwight students, staff, and families.

Regards,

Dr. Toni Jones
Superintendent of Schools

TJ:mb